4455 SE 25th AVE Portland, OR 97202 Phone: 971-512-0691

Name: Prime Motors Y/M/M: 2015 Subaru WRX

VIN:JF1VA2P61F9830117 License: OR Mileage:116000 Date Completed:8/8/2024

Test Drive	
Alignment :	
Good	
Road Test Noise:	
No noise	
ODO Post Test Drive:	

Light Operation	G Y R
Front Low beam	<b>✓</b>
Front High low	<b>✓</b>
Front Turn Signal	<b>✓</b>
Inspection Item 4	<b>✓</b>
Front Day Time Running	<b>✓</b>
Lights	
Front Marker Light	<b>✓</b>
Front Fog Light	<b>✓</b>
Rear Brake Light	<b>✓</b>
Rear Running Lights	<b>✓</b>
Rear Reverse Light	<b>✓</b>
Rar Turn Signals	<b>✓</b>
Rear License Plate Light	<b>✓</b>
Top Brake Light	<b>✓</b>

Vehicle Exterior	G Y R
Front Bumper	<b>✓</b>
Windshield :	
Good	
Hood	<b>✓</b>
Grill	<b>✓</b>
Left Front Fender	<b>✓</b>
Left Front Door	<b>✓</b>
Left Rear Door	<b>✓</b>
Left Quarter Panel	<b>✓</b>
Rear Bumper Cover	<b>✓</b>
Rear Trunk Lid	<b>✓</b>
Right Rear Quarter Panel	<b>✓</b>
Right Rear Door	<b>✓</b>
Right Front Door	<b>✓</b>
Right Front Fender	<b>✓</b>
Roof	<b>✓</b>
Other	<b>✓</b>

Email: Service@primemotorco.com

Technician: Prim, George Service Advisor: Prim, Ruben

## Pre-Purchase Inspection Prime Motors CO Service 4455 SE 25th AVE Portland, OR 97202 Phone: 971-512-0691

Tire Inspection	G Y R	Mechanical	G Y R
TREAL	D DEPTH	Transmission	<b>✓</b>
FRONT		Front Shocks	
Left / 32"	<b>✓</b>	Front Tie Rod(s)	<b>✓</b>
Right / 32"	<b>✓</b>	Front Control Arm	<b>✓</b>
REAR		Front Wheel Bearing	
Left / 32"		Front Steering Rack	<b>✓</b>
Right / 32"		Front Stabilizer Bar/Link(s)	<b>✓</b>
3/32" or greater	2/32" 1/32" or less	Drive Shaft(s)	<b>✓</b>
AIR PRESSURE	WEAR PATTERN	Motor Mount(s)	<b>✓</b>
FRONT Before OEM spec	FRONT	Transmission Mount(s)	<b>✓</b>
Left	Left 🗸	Exhaust Manifold	<b>✓</b>
Right	Right 🗸	Front Outer Brake Pads	50
REAR <sup>psi psi</sup>	REAR	Front Inner Brake Pads	50
Left	Left 🗸 📗	Transfer Case	<b>✓</b>
Right	Right 🗸 📗	Rear Outer Brake Pads	60
psi psi		Rear Inner Brake Pads	60
		Parking Brake	<b>✓</b>
Wheels & Tires	G Y R	Rear Shock(s)	<b>✓</b>
Front Left Wheel		Rear Differential	<b>✓</b>
Rear Left Wheel		Rear Wheel Beasring(s)	<b>✓</b>
Front Right Wheel		Rear Control Arm(s)	<b>✓</b>
Rear Right Wheel	<b>✓</b>	Rear Axle(s)/ Axle boot	<b>✓</b>
Wheel Torque Down			
Mechanical	GYR	Engine Bay	G Y R
Engine		Engine Oil Level	
		Engine Oil Quality	<b>✓</b>

Email: Service@primemotorco.com

Technician: Prim, George Service Advisor: Prim, Ruben

## Pre-Purchase Inspection Prime Motors CO Service 4455 SE 25th AVE Portland, OR 97202 Phone: 971-512-0691

Engine Bay	G Y R	Interior	G Y R
Oil Filter	<b>✓</b>	Front Door Panel Trim	<b>✓</b>
Coolant Level	<b>✓</b>	Rear Door Panel Trim	<b>✓</b>
Coolant Quality	<b>✓</b>	Trunk	<b>✓</b>
Transmission Fluid	<b>✓</b>	Interior Fuse Box	<b>✓</b>
Brake Fluid Level	<b>✓</b>	ABS System	<b>✓</b>
Brake Fluid Quality	<b>✓</b>	Mirror Operation	<b>✓</b>
Washer Fluid Level	<b>✓</b>	Window Operation	<b>✓</b>
Drive Belt(s)	<b>✓</b>	Sunroof	<b>✓</b>
Engine Condition	<b>✓</b>	Interior Lights	<b>✓</b>
Hose(s)	<b>✓</b>	Dash Illumination	<b>✓</b>
Battery	<b>✓</b>	Horn Operation	<b>✓</b>
Air Filter	<b>✓</b>	Airbag System	<b>✓</b>
Cabin Alr Filter	<b>✓</b>	Power Seat Operation	<b>✓</b>
Smoke Test Turbo car	<b>✓</b>	A/C Operation	<b>✓</b>
		Heater Operation	<b>✓</b>
Interior	G Y R	4X4 HI/ 4X4 Low	<b>✓</b>
Front Left Seat	<b>✓</b>	OBD II Scan	<b>✓</b>
Front Right Seat	<b>✓</b>		
Front Seat Belt Operation	<b>✓</b>	Misc.	G Y R
Rear Seat Belt Operation	<b>✓</b>	Spare Tire	<b>✓</b>
2nd Row Seat	<b>✓</b>	Spare Tire Tool Kit	<b>✓</b>
3rn Row Seat	<b>✓</b>	Water Test	<b>✓</b>
Carpet	<b>✓</b>	Wind Test	<b>✓</b>
Headliner	<b>✓</b>	Emission Sticker	<b>✓</b>
DashBoard	<b>✓</b>	Vin Sticker	<b>✓</b>
Center Console	<b>✓</b>	Previous Smoker	<b>✓</b>

Email: Service@primemotorco.com

Technician: Prim, George Service Advisor: Prim, Ruben

Pre-Purchase Inspection
Prime Motors CO Service
4455 SE 25th AVE
Portland, OR 97202

Phone: 971-512-0691

## **Vehicle Trend Analysis**

The following represents items most commonly replaced on 2015 Subaru WRX STI at or around 116000 miles. This list does NOT mean these components have failed on your vehicle. Inspection and/or testing may be advised.

## **Top 10 Component Failures Reported**

- 1. Wheels
- 2. Flywheel
- 3. Disc Brake Pad
- 4. Brake Rotor
- 5. Clutch Kit
- 6. Battery
- 7. Steering Gear
- 8. Tire Valve Stem
- 9. Clutch Master Cylinder
- 10. Spark Plug

Email: Service@primemotorco.com

Technician: Prim, George Page 4 of 4 License 1:
Service Advisor: Prim, Ruben License 2: