

DIGITAL VEHICLE INSPECTION

Point S Affordable Tire & Service

3620 15th Ave W

Seattle, WA 98119

Phone: 206-281-8221

Name: Petty, Jennifer

Y/M/M: 2006 Lexus GX 470

VIN:JTJBT20X660112204 License:CCE7427 AZ Mileage:162000 Date Completed:In Progress

Test Drive	G	Y	R
WARNING LIGHTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wiper Blades/Washer	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Conditioning	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4 Pictures of Vehicle	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exterior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Emergency Brake	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Underhood	G	Y	R
Coolant	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts & Hoses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Radiator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Valve Cover	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Engine Oil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Suspension/Steering	G	Y	R
Front Shocks & Struts	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Shocks & Struts	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Sway Bar Links	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Front Tires	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Suspension/Steering	G	Y	R
Rear Tires	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Ball Joints	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Control Arms	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wheel Bearings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Tie Rods	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Brakes	G	Y	R
Front Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Brakes	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Maintenance	G	Y	R
Cabin Air Filter	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine Mounts	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Timing Belt	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spark Plugs	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fuel Filter	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Differential Fluid	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transfer Case Fluid	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Undercar	G	Y	R
Oil Leaks	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Steering Box/Rack	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
C.V. Joints	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Universal Joints	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

DIGITAL VEHICLE INSPECTION

Point S Affordable Tire & Service

3620 15th Ave W

Seattle, WA 98119

Phone: 206-281-8221

<i>Undercar</i>	<i>G</i>	<i>Y</i>	<i>R</i>
Water Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

DIGITAL VEHICLE INSPECTION

Point S Affordable Tire & Service

3620 15th Ave W

Seattle, WA 98119

Phone: 206-281-8221

DIGITAL VEHICLE INSPECTION

Alternator has failed due to being oil soaked, rec repair oil leaks and replace alternator. Will put battery on charger and see if it is okay, may also need battery.

Wiper Blades/Washer

Blades torn rec replace all 3

Valve Cover

Leaking

Front Shocks & Struts

Leaking

Rear Shocks & Struts

Leaking

Front Tires

Lf date stamped 2010 and bald, other 3 tires from 2017.

Front Brakes

40%

Rear Brakes

30%

Oil Leaks

Valve covers, oil pan, trans cooler hoses, p/s pressure and return hoses, p/s rack

Steering Box/Rack

Leaking

C.V. Joints

Front inner boots torn and leaking

Vehicle Trend Analysis

The following represents items most commonly replaced on 2006 Lexus GX 470 at or around 162000 miles. This list does NOT mean these components have failed on your vehicle. Inspection and/or testing may be advised.

Top 10 Component Failures Reported

1. Disc Brake Pad
2. Brake Rotor
3. Battery
4. Alternator
5. Wheels
6. Brake Caliper
7. Air Conditioning Refrigerant
8. Axle Shaft
9. Turn Signal Light Bulb
10. Radiator